HP CP4525 â€“Easy Steps to Refill the Cartridge and Eliminate the Depleted Toner HP Error Code

by Alyssa Hendricks

Article published on December 9th 2011 | Hardware

HP CP4525 - How to Deactivate the Depleted Toner HP Error Code and Replenish the Cartridge?

Error codes alarm a user that a printer element is not functional. These error codes come out as prompters or messages on the control panel LCD screen of the laser printer such as the HP Color LaserJet CP4525. HP error codes inform the user from a malfunction that requires quick review, from a loosen connection with 1/0 cable (02), to an emptied paper tray (11); a nonexistent cartridge (12) and paper jam (13).

HP error codes are virtually not even associated on toner supply, as specific elements are operating harmonious to render the print caliber anticipated from the printer. Therefore, whenever one factor is uncoordinated, the printer presents the message automatically by its sensors. Simply, if there is one error code that is ought to be of concern to "toner sensitive" HP Color LaserJet CP4525 printer users, so it had better be error code 16 or the depleted toner prompt. This is the sole error code associated with toner supply. The toner deficient message actuates persistently on the LCD screen when standard toner supply degrees are transgressed and if disregarded, the printer will be inactive automatically.

How to nullify error code 16?

To reinstate printer function once more, users have2 choices: (1) purchase an OEM substitute cartridge or (2) establish refills on the emptied toner cartridge utilizing a compatible toner refill kit configured to replenish HP CP4525 cartridges. The option is no longer regulated by toner caliber but of economics because both OEM and compatible toner produce superior laser prints. Then again, the OEM HP CE260A cartridge bears a $145 cost label, whilst the toner refill kit retails for merely $49.95. In replenishing the HP CE260A cartridge, a refill instrument is needed to cut up a fill hole on the polymer shell of the cartridge before compatible toner can be shifted to the toner chamber. The remaining refill procedure is actually very effortless and would likely involve the user fewer than 10 minutes to accomplish it. Here is a concise guide of the homemade refill procedure.

Vacate the toner chamber of utilized toner.

Shift the compatible toner powder of the bottle into the toner chamber.

Thenceforth, seal off the fill hole with electrical tape.

Substitute the reset chip.

Shake up the cartridge back and forth. Mount it back to the printer and execute trial prints.

Finally, Error code 16 reminds the user not of a functional fault of the HP Color LaserJet CP4525 printer but of the depleted toner supply of the HP CE260A cartridge. This can be immediately settled by recharging the drained toner cartridge with compatible toner for HP CP4525 cartridges.

Article Source:

http://www.articleside.com/hardware-articles/hp-cp4525-easy-steps-to-refill-the-cartridge-and-eliminate-the-depleted-toner-hp-error-code.htm - Article Side

Alyssa Hendricks - About Author:
For your laser printing requirements, check out Toner Refill Store for its line of toner refill kits, a HP laser printer ink toner cartridgeand other affordable printer consumables.

Article Keywords:
hp toner cartridge, hp laser printer ink toner cartridge, hp laser toner cartridge, hp toner, hp laser jet toner

You can find more free articles on Article Side. Sign up today and share your knowledge to the community! It is completely FREE!